

FIGURE 1

PRIOR ART




FIGURE 2




Figure 3



FORMING A POLARIZING FILM 30 BY LAMINATING A TAC FILM OR CAB FILM 34 AND A DRAWN PVA FILM 36



LAMINATING THE POLARIZING FILM 30 ONTO A TRANSPARENT SUPPORT 5 WITH AN ADHESIVE AGENT INTERPOSED 34



CUTTING AWAY PORTIONS OF POLARIZING FILM 30 WITH A ULTRA-HARD BLADE IN SPECIFIED POSITIONS (a) AS SHOWN



LEAVING SPACES 26(b) BETWEEN THE REMAINING PORTIONS OF POLARIZING FILM 30(a) EMPTY



ATTACHING PROTECTIVE MEMBER 22 TO THE POLARIZING FILM AND EMPTY SPACES



BONDING THE LAMINATED POLARIZED FILM 34 SIDE OF THE PROTECTED ASSEMBLY TO A DISPLAY MEMBER 5

FIGURE 4




FIGURE 5